

IN THE CIRCUIT COURT FOR THE FIFTEENTH JUDICIAL CIRCUIT
IN AND FOR PALM BEACH COUNTY, FLORIDA.
CRIMINAL DIVISION

STATE OF FLORIDA,

CASE NO. 50-2010-CF-005829 AMB

Plaintiff,

vs.

JOHN B. GOODMAN,

Defendant.

FILED
15 DEC -3 PM 1:48
CLERK OF COURT
CRIMINAL DIVISION

AGREED ORDER RE: DEFENSE INSPECTION OF BENTLEY

The above-styled cause came before the Court upon the Agreement of the State and the Defense that Defense experts may conduct an inspection/examination of the Bentley automobile as follows:

1. The expert will bring a battery (compatible with this model Bentley), Bentley Diagnostic Tool, all needed hand tools, and photography/videography equipment to the inspection and will do the following:
2. Perform a thorough physical inspection, manual manipulation, and photographing/videoing of the throttle body(ies), including all internal parts (butterfly valve(s)), butterfly valve shaft(s), position sensors, rotational motors, electrical plugs/connectors, and the plastic cover over the electronics on the throttle body.
3. Perform a thorough physical inspection, manual manipulation, and photographing/videoing of the vehicle hood, vehicle hood brackets, and vehicle hood mounting hardware, and perform testing/analysis of vehicle hood damage / vehicle hood position in relation to throttle body. If the hood has been removed from the vehicle, reinstall hood prior to testing.
4. Perform a thorough physical inspection, manual manipulation, and photographing/videoing of the vehicle's seatbelt system including the seatbelt webbing, seatbelt buckle, seat buckle receiver, retractor mechanism, pretensioning system including pyrotechnic device, mounting hardware, and

seatbelt guides.

5. Perform a thorough physical inspection, manual manipulation, and photographing/videoing of the vehicle's rear brake system to determine if this particular Bentley is properly included in the recall initiated by Bentley and whether any of the retaining bolts are broken/damaged.
6. Perform a thorough physical inspection, manual manipulation, and photographing/videoing of the vehicle's airbag system (SRS) including the airbags, airbag containers, and airbag electronics including airbag sensors.
7. Perform electronic diagnostics tests on the vehicle's Electronic Control Modules, and all vehicle engine management electronics, including but not limited to the electronics contained on the throttle bodies.
8. Download all "fault codes" from the vehicle's Electronic Control Modules.
9. Download data contained in the vehicle's airbag sensors/electronics.
10. Perform diagnostic tests similar to those performed by Thomas Livernois, specifically our expert will cycle the electronic system and attempt to reproduce the "fault codes" produced by Livernois and will analyze the data downloaded from the Electronic Control Modules. He will generate "fault codes" by both removing the plug on the throttle body (as Livernois did) and will also manually restrain the butterfly valve in order to ascertain what, if any, differences result in the "fault codes" logged in the Electronic Control Modules. In addition, our expert will perform similar tests to those Livernois conducted relating to how the Electronic Control Modules log fault code occurrences.
11. Take measurements of exterior and interior of Bentley.

It is further, Stipulated and Agreed that the Defense shall video this examination/

State v. John Goodman
Case No. 50-2010-CF-005829 AMB
Agreed Order Re: Defense Inspection of Bentley
Page 3

inspection and a copy of said video will be provided to the State.

DONE AND ORDERED this 2 day of December, 2013, Palm Beach County, West
Palm Beach, Florida.



JEFFREY COLBATH
Circuit Judge

Copies furnished:

Douglas Duncan, Esquire, P.O. Box 770, West Palm Beach, FL 33402
Scott N. Richardson, Esquire, 1401 Forum Way, Suite 720, West Palm Beach, FL 33401
Elizabeth Parker, Esquire, 515 N. Flagler Drive, Suite 325, West Palm Beach, FL 33401
Alan Johnson, Esquire, Chief Assistant State Attorney
Sherri Collins, Esquire, Assistant State Attorney